

CDM Regulations

CDM AWARE!

Ha⊪

Lift

Dental

Room # 4

Dental

Room # 5

Kitchenette

Store

Roòm

Dental

Room # 3

Store

Room

Lobby

Denotes a significant Hazard or difficult to manage procedure. Please refer to Designer Hazard Register for further information regarding mitigation of hazards

Existing floor joists to remain unaltered.

New 2x75x200mm s.w. C24 flitch beam with a 15x195mm mild steel plate fixed between using M12 bolts at 450mm c/c's max.

2no. new additional 50x225mm C24 s.w. floor joists to span between new double trimmers and bolted together.

\_\_ Existing floor joists to be trimmed back.

New 2x75x200mm s.w. C24 flitch beam with a 15x195mm mild steel plate fixed between using M12 bolts at 450mm c/c's max.

New fixed stairs to be installed from second floor to third floor apartment above.

CLAPTEDED CIVIL R. CTENCTUDAL ENCINEEDING CONCULTANTS

Osborn House, 20 High Street South, Olney, Bucks.

MK46 4AA.

t.01234 240640 t.01234 240644 f.01234 713042

General Notes

Do not scale off this drawing unless a scale bar is provided.

Any ambiguities, omissions and errors on this drawing should be notified immediately to the Architect before the commencement of works on site.

All dimensions are in millimetres unless otherwise stated.

All dimensions, unless otherwise indicated, are to the face of unfinished block walls or to the rough timber face of stud partitions.

All dimensions are to be checked on site. Any discrepancies are to be notified immediately to the Architect before the commencement of works on site.

All levels are in meters unless otherwise stated.

This drawing is to be read in conjunction with all other relevant drawings and specifications for this project.

Rev	Description	ВУ	Date
P1	First issue.	swf	01.12.11
P2	Stairs amended.	swf	15.12.11
P3	Proposed trimmers changed to flitch beams. Existing floor joist amended following exposure.  Notes added	swf	12.01.12

## NOTES TO CONTRACTOR

- Party wall agreements will be in place with all affected tenants prior to any commencement of works. The contractor/sub-contractor must familiarise themselves with the agreements and adhere to there contents. Any breech will be the responsibility of the contractor/sub-contractor to rectify.
- Access to the third floor flat and area or works is via the
  front main entrance door and stairs. The door and
  entrance area are fairly wide but the door to the upper
  floor and the existing stairs are very tight for space. It is
  strongly advised that all prospective contractors and/or
  sub-contractord visit the site before completing their
  assessment for construction and pricing.
- 3. The contractor and/or sub-contractor is responsible for the safe and clean removal of all unused materials, tools, debris and general rubbish from the site. Allowance must be made for the protection of existing elements, i.e. doors, walls, stairs etc. Any damage must be repaired or replaced and the contractor/sub-contractors expense to the agreement and satisfaction of all tenants and the client.



Survey Drawings

,		
sed Second		
1:50 @ A2	Drawn	SWF
01.12.11	Checked	AA
107/	Drawing No.	Revision
	-	1:50 @ A2 Drawn 01.12.11 Checked No./Dicipline Drawing No.

Existing Second Floor (showing structure above)